














Identification du réservoir à encastrer existant					Rééquipement		
Plaque de déclenchement	Cloche	Réservoir à encastrer	N° PA	Année de fabrication	Kit de transformation	Plaque de déclenchement	
Rééquipement avec déclenchement de l'interruption du rinçage							
		15.000	PA-I/1115	1964-1967	215.420.00.1	115.222.xx.1	
		16.000		1965-1967	215.421.00.1		
		10.500	PA-I/IX1884/I	1970-1974	215.422.00.1		
		10.520	PA-I/IX1885/I	1970-1974			
		10.600	PA-I 1637 PA-I/X1886/I	1967-1971 1971-1974 1974-1978	215.423.00.1		
		10.620	PA-I/IX1887/I	1967-1974			
		10.800	PA-I/IX2331/I	1975-1977	240.026.00.1		
		10.400	PA-I/IX2760/I	1978-1986			
Rééquipement avec rinçage double touche							
		10.800 ¹⁾	PA-I/IX2761/I	1978-1987	240.835.00.1		115.888.xx.1
		110.800 ²⁾	PA-I/IX2761/I PA-I/IX1153/I PA-I/IX1153	1988-1997	240.515.00.2		

¹⁾ Plaque de protection transparente, vis de fixation en laiton

²⁾ Plaque de protection blanche